

```
1: =====
2: Actiontec ScreenBeam FW Release Notes
3: =====
4: Date 2016-07-01
5: FW Version: 1.3.11.0
6: -----
7: Summary of Changes since 1.3.10.0
8: -----
9:
10: Fix: UIBC incompatibility with certain mouse/keyboard sets
11: Fix: Video freeze when using UIBC continuously for an extended period
12: Fix: Cursor offset when using resolution 1600x1024
13: Fix: Flash file system may get corrupted causing device to not boot up properly
14: Fix: Mouse tracking is off when switching out and back to the HDMI port
15: Fix: When using configuration utility and exiting, the device does not return to
    Ready state
16:
17: Feature: Changed Intel WiDi logo
```