

=====
Actiontec ScreenBeam Mini2 Firmware Release Notes
=====

Date 2018-01-15

FW Version: 5.3.15.0

CHANGES SINCE 5.3.14.0

1. Fix bug: Other configuration items would be lost when configuration the default language (factory configure).
2. Re-configure audio FW when the audio sample rates change with different Miracast sources.
3. Fix issue: Mouse cursor disappears in external display when connect via Miracast.
4. Sync with sink-1185-be codes about Actiontec MAC OUI.
5. Add Actiontec MAC OUI.